

DART SERVICE BULLETIN SB10-2

AFFECTING:

**D407-663-011 HELI-UTILITY-BASKET AT CHG 002 OR EARLIER
& D407-627-013 HELI-UTILITY-POD AT CHG 004 OR EARLIER**

**REF. TCCA STC: SH98-57, SH00-28
REF. FAA STC: SR01246NY, SR01365NY**

For aircraft equipped with a **cargo hook** and either **D407-628-013 *Heli-Utility-Pod* at CHG 004 or earlier** or **D407-663-011 *Heli-Utility-Basket* at CHG 002 or earlier**, the manual release cable may become caught on the DART installation should a misalignment exist. The DSI-9428-011 Cable Connection Guard Kit must be installed on affected installations to prevent interference with the manual release cable. Refer to DART service instruction DSI 9428 for further details.

D407-628-013 *Heli-Utility-Pod* at CHG 005 or later, and D407-663-011 *Heli-Utility-Basket* at CHG 003 or later, are unaffected by this issue.

A	NEW ISSUE	CP	10.04.23
REV.	DESCRIPTION	BY	DATE
DESIGN	<i>qp</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	<i>qp</i>		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	SB10-2	SHEET 1 OF 1
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	SERVICE BULLETIN	NTS
DATE	10.04.23	COPYRIGHT © 2010 BY DART AEROSPACE LTD <small>THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.</small>	